

No.: SB-SC-100

**DATE:** 2023-10-06

**PAGE:** 1/2

## **SERVICE BULLETIN**

Czech Aircraft Group s.r.o. Na Záhonech 212 686 04 Kunovice Czech Republic info@cruiseraircraft.cz

REV.: -

DATE: -

MODEL AFFECTED:	SportCruiser / PiperSport operating outside EASA rules
SUBJECT:	BRS Parachute Removal
AIRCRAFT AFFECTED:	
COMPLIANCE:	According to the owner's decision

## **DESCRIPTION:**

This Service Bulletin contain instructions how to remove BRS parachute.

#### **AUTHORISATION TO PERFORM:**

Repairman (LS-M) or Mechanic (A&P)

### **MANPOWER:**

3 hours

### **SPECIAL TOOLS:**

Common tools for aircraft maintenance.

### **WEIGHT AND BALANCE:**

Affected.

## **ELECTRICAL LOAD DATA:**

N/A

## **PUBLICATIONS AFFECTED:**

POH - Pilot's Operating Handbook

### **MATERIAL AND COSTS:**

All costs to be covered by the aircraft owner / operator.



**No.:** SB-SC-100

**DATE:** 2023-10-06

**PAGE**: 2/2

# **SERVICE BULLETIN**

Czech Aircraft Group s.r.o. Na Záhonech 212 686 04 Kunovice Czech Republic info@cruiseraircraft.cz

REV.: -

DATE: -

## **ACCOMPLISHMENT INSTRUCTIONS:**

See Installation instruction, Doc. No. II-CR-004, latest revision.

NOTE: Installation instruction, Doc. No. II-CR-004 is available upon request for a fee.

### **INFORMATION:**

For more detailed information contact Czech Aircraft Group at info@cruiseraircraft.cz.

## **APPROVAL:**

This Service Bulletin has been approved by:

TITLE:	Head of Design Organisation	Airworthiness Manager
NAME:	David Bilík	Jan Pejchar
HAND WRITTEN SIGNATURE:	Bilik	Gh