Czech Sport Aircraft a.s.

No. SB-SC-901 Date: 2015-03-04 Page: 1 of 2

SERVICE BULLETIN

Czech Sport Aircraft a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com

Rev.: -

Date: -

MODEL AFFECTED:	SportCruiser
SUBJECT:	Transition of SportCruiser aircraft for the Permanent Flight Conditions (P-FC)
AIRCRAFT AFFECTED:	S/N 09SC285

DESCRIPTION:

Czech Sport Aircraft a. s. in accordance with the EASA document "Transition period for LSA aircraft under Permit to Fly" issues the following SB-SC-901 in order to transfer and qualify the SportCruiser aircraft S/N 09SC285 for the Permanent Flight Conditions (P-FC).

For this purpose the following changes must be done on the subjected aircraft:

- 1) Implementation of the Service Bulletin SB-SC-026, that provides the oil system hoses replacing and the pyro-jackets installation.
 - (to be performed by any Part-M, Part 145 organization or CSA)
- Implementation of the Service Bulletin SB-SC-027, that provides an installation of modified aircraft position lights.
 (to be performed by any Part-M, Part 145 organization or CSA)
- 3) Implementation of the Service bulletin SB-SC-028, that provides straps installation in the baggage compartment.
 - (to be performed by any Part-M, Part 145 organization or CSA)
- 4) Issuance of a new Pilot's Operating Handbook valid for specific airplane serial number, including change of rear C.G. position (35 % of MAC), different wing flaps setting for takeoff (12°) and the other changes resulting from the airplane equipment. (to be performed by CSA)
- 5) Performing the aircraft inspection for physical condition checking, in order to prepare the Data Sheet. (to be performed by CSA)*
- Assistance to the aircraft owner for the FC Approval drafting of new Form 18B and managing the process with EASA.
 (to be performed by CSA)
- 7) Elaborate the Aircraft Data Sheet technical specifications (necessary for the FC Approval). (to be performed by CSA)
- 8) Handover the design responsibility for individual aircraft to the aircraft owner (elaborating of handover protocol).
- *) This item is possible to be carried out in Kunovice or in a customer site with the presence of the CSA staff.

AUTHORISATION TO PERFORM:

See above for each item separately.

COSTS TO BE COVERED BY:

Operator

REFERENCES:

- SportCruiser / PiperSport Airplane Maintenance Manual, SC-AMM-1-0-00, latest edition
- AC 43.13-1B, Acceptable Methods, Techniques, and Practices Aircraft Inspection and Repair
- EASA document "Transition period for LSA aircraft under Permit to Fly"

Czech Sport Aircraft a.s.

No. SB-SC-901 Date: 2015-03-04

Page: 2 of 2

SERVICE BULLETIN

Czech Sport Aircraft a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com

Rev.: -

Date: -

PUBLICATIONS AFFECTED:

SportCruiser / PiperSport Airplane Maintenance Manual, SC-AMM-1-0-00, latest edition

NEWLY ISSUED PUBLICATIONS:

SportCruiser S/N 09SC285 Pilot's Operating Handbook, Doc. No. POH-09SC285 SportCruiser S/N 09SC285 Data Sheet

APPROVAL:

This SB was approved by:

Title	Head of the Design Organisation	Airworthiness Manager
Name	Jiří Konečný	Marek Kotolan
Hand written signature	Low	tal