



REVIEW of SUPPLEMENTS to SC-AMM-1-0-00

DESCRIPTION AND OPERATION

1. **General**

This Chapter contains supplementary information on the optional equipment which is installed in the airplane.

The information given in this Chapter complete or supersede the basic Maintenance Manual in those sections as specified. Where not otherwise stated, information shown in the basic Maintenance Manual remains effective. Each Supplement consists of a Title Page, Record of Revisions, List of effective pages and the proper text.

2. **List of supplements**

No.	Content	Note
01	Inspection and / or replacement of the valve Push-Rod-Assy., Rocker arm for ROTAX® engine type 912 S2 and 912 ULS2	
02	Additional BC425-H alternator	



3. List of airplane S/N covered by the supplement

Airplane model	Serial No.	Supplement No.	Note
PS-28 Cruiser, SportCruiser / PiperSport – operating under EASA PFC	C0589, C0590, C0601, C0602, C0603, C0604, C0605, C0606, C0607 and all further aircraft the engine of which have been equipped with valve push-rod assy. part no.854861 during engine repair, maintenance or general overhaul as of May 01 to 30 November 2017, inclusive.	01	-
SportCruiser / PiperSport – operating out of EASA rules	-	02	Valid only for those airplanes the owners of which decide to install the additional BC425-H alternator