



CRUISER
AIRCRAFT

No.: SB-SC-002

DATE: 2010-09-23

PAGE: 1/4

SERVICE BULLETIN

Czech Aircraft Group s.r.o.
Na Záhonech 212
686 04 Kunovice
Czech Republic
info@cruiseraircraft.cz

REV.: 1

DATE: 2021-12-02

MODEL AFFECTED:	SportCruiser / PiperSport operating outside EASA rules
SUBJECT:	Issue of POH Supplement No. 03
AIRCRAFT AFFECTED:	All SportCruiser / PiperSport aircraft Aircraft serial numbers S/N P1001060 and subsequent will have the subject of this bulletin accomplished in appropriated chapters of POH.
COMPLIANCE:	Within 25 flight hours.

DESCRIPTION:

Service Bulletin concerns issue of POH Supplement No. 3. There were several cases in operation, when due to unlatched canopy the canopy opened during flight. Information in this Supplement completes or replaces information in the basic Pilot's Operating Handbook concerning to unlatched canopy.

AUTHORISATION TO PERFORM:

Pilot/Owner

MANPOWER:

0,5 hour

REFERENCES:

SportCruiser POH
PiperSport POH

PUBLICATIONS AFFECTED:

SportCruiser POH
PiperSport POH



CRUISER
AIRCRAFT

No.: SB-SC-002

DATE: 2010-09-23

PAGE: 2/4

SERVICE BULLETIN

Czech Aircraft Group s.r.o.
Na Záhonech 212
686 04 Kunovice
Czech Republic
info@cruiseraircraft.cz

REV.: 1

DATE: 2021-12-02

ACCOMPLISHMENT INSTRUCTIONS:

- 1) Download appropriate Supplement No. 03 from <https://cruiseraircraft.cz/tech-publications/>
POH Supplement No 3_1 is valid to S/N:
06SC008, 06SC020, 06SC041, 07SC01 4, 07SC015, 07SC016, 07SC017, 07SC019,
07SC020, 07SC021, 07SC022, 07SC026, 07SC027, 07SC028, 07SC029, 07SC031,
07SC033, 07SC034, 07SC035, 07SC036, 07SC038, 07SC039, 07SC040, 07SC041,
07SC043, 07SC044, 07SC045, 07SC046, 07SC050, 07SC051, 07SC054, 07SC056,
07SC059, 07SC061, 07SC062, 07SC063, 07SC067, 07SC068, 07SC071, 07SC074,
07SC075, 07SC076, 07SC078, 07SC081

POH Supplement No 3_2 is valid to S/N:
06SC037, 06SC038, 07SC018, 07SC024, 07SC025, 07SC032, 07SC042, 07SC047,
07SC052, 07SC053, 07SC055, 07SC060, 07SC064, 07SC065, 07SC066, 07SC069,
07SC070, 07SC077, 07SC079, 07SC082, 07SC083, 07SC084, 07SC085, 07SC086,
07SC090, 07SC091, 08SC087, 08SC088, 08SC089, 08SC093, 08SC094, 08SC098,
08SC099, 08SC100, 08SC101, 08SC102, 08SC104, 08SC105, 08SC106, 08SC109,
08SC110, 08SC111, 08SC112, 08SC115, 08SC117, 08SC121, 08SC125, 08SC126,
08SC129, 08SC132, 08SC133, 08SC134, 08SC135, 08SC136, 08SC139, 08SC140,
08SC142, 08SC143, 08SC144, 08SC149, 08SC150, 08SC155, 08SC156, 08SC157,
08SC158, 08SC159, 08SC167, 08SC168, 08SC169, 08SC172, 08SC173, 08SC176,
08SC179, 08SC185, 08SC189, 08SC190, 08SC193, 08SC194, 08SC195, 08SC199,
08SC200, 08SC203, 08SC204, 08SC207, 08SC208, 08SC211, 08SC212, 08SC215,
08SC218, 08SC219, 08SC223, 08SC224, 08SC225, 08SC228, 08SC229, 08SC231,
08SC232, 08SC237, 08SC238, 08SC241, 08SC242, 08SC243, 08SC244, 09SC165,
09SC166, 09SC246, 09SC247, 09SC248, 09SC249, 09SC252, 09SC254, 09SC257,
09SC258, 09SC262, 09SC263, 09SC264, 09SC265, 09SC266, 09SC267, 09SC268,
09SC270, 09SC273, 09SC275, 09SC276, 09SC277, 09SC278, 09SC279, 09SC280,
09SC281, 09SC282, 09SC283, 09SC284, 09SC286, 09SC287, 09SC288

POH Supplement No 3_3 is valid to S/N:
09SC274, 09SC289, 09SC291, 09SC295, 09SC304

POH Supplement No 3_4 is valid to S/N:
09SC293, 09SC300, 09SC301, 09SC309, 09SC311, 09SC329



CRUISER
AIRCRAFT

No.: SB-SC-002

DATE: 2010-09-23

PAGE: 3/4

SERVICE BULLETIN

Czech Aircraft Group s.r.o.
Na Záhonech 212
686 04 Kunovice
Czech Republic
info@cruiseraircraft.cz

REV.: 1

DATE: 2021-12-02


POH Supplement No 3_5 is valid to S/N:

10SC290, P1001001, P1001002, P1001003, P1001004, P1001005, P1001006,
P1001007, P1001008, P1001009, P1001010, P1001011, P1001012, P1001013,
P1001014, P1001015, P1001016, P1001017, P1001018, P1001019, P1001020,
P1001021, P1001022, P1001023, P1001024, P1001025, P1001026, P1001027,
P1001028, P1001029, P1001030, P1001031, P1001032, P1001033, P1001034,
P1001035, P1001036, P1001037, P1001038, P1001039, P1001040, P1001041,
P1001042, P1001043, P1001044, P1001045, P1001046, P1001047, P1001048,
P1001049, P1001050, P1001051, P1001052, P1001053, P1001054, P1001055,
P1001056, P1001057, P1001058, P1001059

- 2) Print downloaded pages.
- 3) Insert appropriate POH Supplement No. 03 behind the current last page of POH.
- 4) Update aircraft records to reflect compliance with this Service Bulletin.

APPROVAL:

This Service Bulletin has been approved by:

TITLE:	Head of Design Organisation	Airworthiness Manager
NAME:	Jiří Sklenář	Jiří Sklenář
HAND WRITTEN SIGNATURE:		



CRUISER
AIRCRAFT

No.: SB-SC-002

DATE: 2010-09-23

PAGE: 4/4

SERVICE BULLETIN

Czech Aircraft Group s.r.o.

Na Záhonech 212

686 04 Kunovice

Czech Republic

info@cruiseraircraft.cz

REV.: 1

DATE: 2021-12-02

INTENTIONALLY LEFT BLANK
