

Czech Sport Aircraft a.s.	<b>SERVICE BULLETIN</b>	Czech Sport Aircraft a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com
No. SB-CR-018		Rev.: -
Date: 2014-01-21		
Page: 1 of 1		Date: -

<b>MODEL AFFECTED:</b>	PS-28 Cruiser / SportCruiser / PiperSport
<b>SUBJECT:</b>	Optional installation of enhanced heating system and blowers for defogging of the windscreen shield
<b>AIRCRAFT AFFECTED:</b>	All PS-28 Cruiser aircraft produced. All SportCruiser aircraft produced. All PiperSport aircraft produced.
<b>COMPLIANCE:</b>	According to aircraft owner decision.

**DESCRIPTION:**

Aircraft manufacturer offer the installation kit for the optional installation of enhanced heating system and blowers for defogging the windscreen shield.

**APPROVAL:**

Optional installation of enhanced heating system and blowers for defogging the windscreen shield is EASA approved as a Minor Change Approval 10045960, dated 31 July 2013.

**AUTHORISATION TO PERFORM:**

US: Repairman (LS-M) or Mechanic (A&P). Europe & Elsewhere: EASA Part M Engineering organization.

**MANPOWER:**

Approximately 30 hours are required to complete installation of enhanced heating system and blowers for defogging the windscreen shield. Man-hours are based on hands-on time, and may vary with personnel and facilities available.

**WEIGHT AND BALANCE:**

Affected.

**ELECTRICAL LOAD DATA:**

Affected.

**MORE DETAILED INFORMATION:**

For more detailed information contact Czech Sport Aircraft at [sales@czechsportaircraft.com](mailto:sales@czechsportaircraft.com)

**APPROVAL:**

This SB was approved by:

<b>Title</b>	Head of the Design Organisation	Airworthiness Manager
<b>Name</b>	Jiří Konečný	Marek Kotolan
<b>Hand written signature</b>		