

Czech Sport Aircraft a.s.	SERVICE BULLETIN	Czech Sport Aircraft a.s. Na Záhonech 1177/212, 686 04 Kunovice Czech Republic office@czechsportaircraft.com
No. SB-SC-019		Rev.: -
Date: 2014-02-11		
Page: 1 of 1		Date: -

MODEL AFFECTED:	PS-28 Cruiser
SUBJECT:	Optional installation of Sensenich 3B0R5R68C propeller
AIRCRAFT AFFECTED:	All PS-28 Cruiser aircraft produced.
COMPLIANCE:	According to aircraft owner decision.

DESCRIPTION:

Aircraft manufacturer offer the Optional installation of Sensenich 3B0R5R68C propeller.

APPROVAL:

Optional installation of Sensenich 3B0R5R68C propeller is EASA approved as a Major Change Approval 10047966, dated 31 January 2014.

AUTHORISATION TO PERFORM:

EASA Part M or Part 145 Maintenance organization.

MANPOWER:

Approximately 2 hours are required to complete Sensenich 3B0R5R68C propeller installation. Man-hours are based on hands-on time, and may vary with personnel and facilities available.

WEIGHT AND BALANCE:

Affected.

ACCOMPLISHMENT INSTRUCTIONS:

II-SC-002, latest effective issue must be complied with.

MORE DETAILED INFORMATION:

For more detailed information contact Czech Sport Aircraft at sales@czechsportaircraft.com

APPROVAL:

This SB was approved by:

Title	Head of the Design Organisation	Airworthiness Manager
Name	Jiří Konečný	Marek Kotolan
Hand written signature		