Czech Sport Aircraft, a.s.

No. SB-PS-023 Date: 2014-07-10 Page: 1 of 1

SERVICE BULLETIN

Czech Sport Aircraft, a.s.
Na Záhonech 1177/212,
686 04 Kunovice
Czech Republic
office@czechsportaircraft.com

Rev.: -

Date: -

MODEL AFFECTED:	PS-28 Cruiser	
SUBJECT:	Issue of the POH PS-POH-1-1-11, Revision 2 Issue of the POH PS-POH-1-1-12, Revision 2	
AIRCRAFT AFFECTED:	PS-28 Cruiser S/N C0272, C0290, C0322, C0409, C0412, P1102002, C0422, C0433, C0435, C0438, P11002024, C0443, C0444, C0445, C0447, C0448, C0449, C0450, C0451, C0452, C0455, C0457, C0458, C0459, C0461, C0466, C0468, C0469, C0470, C0472, P1102040, C0475, C0476, C0478, C0479, C0485, C0487, C0488, C0489, C0498, C0500, C0506, C0507, C0508, C0509, C0511, C0512	
COMPLIANCE:	After receipt of this SB.	

DESCRIPTION:

The Service Bulletin concerns the issuance of the PS-28 Cruiser POH PS-POH-1-1-11, Revision 2; and PS-28 Cruiser POH PS-POH-1-1-12, Revision 2.

This revision provides supplementation of maximal empty weight value and correction of maximal fuel pressure limit value.

AUTHORISATION TO PERFORM:

Pilot / Owner

MANPOWER:

REFERENCES:

POH PS-POH-1-1-11 POH PS-POH-1-1-12

PS-POH-1-1-11 is intended for aircraft equipped with a Dynon D100/120 screens; PS-POH-1-1-12 is intended for aircraft equipped with conventional analog instruments.

PUBLICATIONS AFFECTED:

POH PS-POH-1-1-11 POH PS-POH-1-1-12

ACCOMPLISHMENT INSTRUCTIONS:

- Download the appropriate pages of the PS-28 Cruiser POH PS-POH-1-1-11, Revision 2 or PS-28 Cruiser POH PS-POH-1-1-12, Revision 2 from 05 June 2014.
- 2. Print the downloaded pages.
- 3. Insert the pages of Revision 2 instead of the current appropriate pages, discard the old one.
- 4. Update aircraft records to reflect the compliance with this SB.

APPROVAL:

This Service Bulletin is approved by:

Title	Head of the Design Organization	Airworthiness Manager
Name	انز Konečný الم	Marek Kotolan
Hand written signature	X.	