



SUPPLEMENT NO.5 TO DOC.NO. CR-WMA-1-0-01

COCKPIT LIGHT REPLACEMENT

As the production of the original cockpit light type W003-MiniSpot (series) has been terminated, the original cockpit light is replaced by the new one – type Accent-2580-10-30V cockpit light.

LIST OF AIRPLANES COVERED BY THIS SUPPLEMENT

Airplane model	Serial No.	Note
PS-28 Cruiser	-1)	-

1) Valid also for all aircraft equipped with the cockpit light, type Accent-2580-10-30V as a replacement.

LIST OF WIRING DIAGRAMS COVERED BY THIS SUPPLEMENT

Title	Dwg. No.	Page
INTERNAL LIGHTING	SI1017N	4



RECORD OF REVISIONS

Rev. No.	Revision name	Changed pages	Issue date	Date and signature

