



**SUPPLEMENT NO.1 TO DOC.NO. CR-WMA-1-0-04**

**INSTALLATION OF GARMIN APOLLO SL30 NAV/COMM WITH CDI  
GARMIN MD200-306**

**LIST OF AIRPLANES COVERED BY THIS SUPPLEMENT**

Airplane model	Serial No.	Note
PS-28 Cruiser	C0412	-

**LIST OF WIRING DIAGRAMS COVERED BY THIS SUPPLEMENT**


Title	Dwg. No. ....	Page
ENGINE ROTAX 912	SI0355N .....	4
SL-30	SI0357N .....	5
INTERNAL LIGHTING	SI0369N .....	6



**RECORD OF REVISIONS**


Rev. No.	Revision name	Changed pages	Issue date	Date and signature
1	Administrative corrections in drawings, Name of Circuit Breaker 25A 2TC2 changed to 11-08382, name of Circuit Breaker Klixton 2TC2 changed to MS3320	2, 3, 4, 5, 6	2015-09-07	2015-09-07 Konečný







Supplement No.1 to CR-WMA-1-0-04



Block Type	PS-28 Cruiser	Block No.	SI0357N
Title	SL-30	Block Address	

